


PARTS LIST FOR OPTIMARC® CV350




ILLUSTRATION OF SUB-ASSEMBLIES



OPTIMARC® CV350



Index of Sub Assemblies
Index of Sub Assemblies
Index of Sub Assemblies



OPTIMARC® CV350



ITEM	DESCRIPTION	PART NO.	QTY.	1						76241	1
1	Case Front Welded Assembly	G5874-10	1	X							
1a	M5X12 Hex Washer Head Philips (Not Shown)	S26641-4	3	X							
1b	ST4.8X13 Washer Faced Hex Self (Not Shown)	S26738-2	1	X							
2	Control Nameplate	G6082-49	1	X							
3	Signal Lamp Assembly	S29850-1	1	X							
4	Knob	T13639-6	3	X							
4a	O Ring (Not Shown)	T13483-34	3	X							
5	Copper Strap (Main Transformer to Shunt)	S27092-21	1	X							
6	Shunt	S26194-1	1	X							
6a	M8X40 Carriage Bolt (Not Shown)	S27072-2	1	X							
6b	M8X40 Hex Head Screw (Not Shown)	S26641-9	1	X							
6c	M8 Plain Washer (Not Shown)	S26638-4	3	X							
6d	M8 Lock Washer (Not Shown)	S26639-4	2	X							
6e	M8 Hex Nut (Not Shown)	S26640-4	2	X							
7	Output Stud	M20710-1	2	X							
7a	M5 Hex Head Screw (Not Shown)	S26641-5	4	X							
7b	M6 Plain Washer (Not Shown)	S26638-8	8	X							
7c	M5 Lock Washer (Not Shown)	S26639-3	4	X							
7d	M5 Hex Nut (Not Shown)	S26640-3	4	X							
7e	MOV Assembly for Output (Not Shown)	S27147-4	1	X							
8a	M10X22 Carriage Bolt	S27072-1	2	X							
8b	M10 Hex Nut (Not Shown)	S26640-6	2	X							
8c	M10 Plain Washer (Not Shown)	S26638-6	2	X							
8d	M10 Lock Washer (Not Shown)	S26639-6	2	X							
9	Knob	T10491-7	1	X							
9a	O Ring (Not Shown)	T13483-34	1	X							
10	Door	L13141	1	X							
10a	Spring Clip	S27348	2	X							
10b	Output Stud Door Decal (Not Shown)	M21174-9	1	X							
11	Wire Feeder Harness (Not Shown), Includes:	G6043-37	1	X							
11a	6 Pin Control Socket	S26179	1	X							
11b	M3 Flat Head Philips Screw (Not Shown)	S26641-1	3	X							
11c	M3 Plain Washer (Not Shown)	S26638-1	3	X							
11d	M3 Lock Washer (Not Shown)	S26639-1	3	X							
11e	M3 Hex Nut (Not Shown)	S26640-1	3	X							
13	Potentiometer Spacer	S18280	3	X							
14	Display & Pot Harness (Not Shown), Includes:	G6043-35	1	X							
14a	Potentiometer	T10812-127	3	X							
15	Display Board Assembly	S29835	1	X							
16	Toggle Switch, SPST	T10800-4	2	X							
17	Toggle Switch, SPDT	T10800-23	1	X							
18	Switch Harness (Not Shown), Includes:	G6043-34	1	X							
18a	3 Position Rotary Switch (Weld Mode Switch)	S16670-21	1	X							
19a	Switch Cover	S27281	1	X							
19b	Switch Bracket Welded Assembly	M21705	1	X							
19c	Line Switch	S27016	1	X							
See next page for more.											

NOTE: Use only the parts marked "X" in the column under the heading number called for in the model index page.

OPTIMARC® CV350




2017.04

(Continued)

ITEM	DESCRIPTION	PART NO.	QTY.	1					76241	1
19d	Din Rail	S27200	1	X						
19e	M5X12 Combined Screw	S28798-4	2	X						
19f	M4 Plain Washer (Not Shown)	S26638-2	4	X						
19g	M4 Lock Washer (Not Shown)	S26639-2	4	X						
19h	M4 Hex Nut (Not Shown)	S26640-2	4	X						
20	Case Front Nameplate	G6082-48	1	X						

NOTE: Use only the parts marked "X" in the column under the heading number called for in the model index page.


Index of Sub Assemblies
 Sub Assembly Illustration
 Index of Sub Assemblies
 Sub Assembly Illustration
 Index of Sub Assemblies
 Sub Assembly Illustration
 Index of Sub Assemblies
 Sub Assembly Illustration



ITEM	DESCRIPTION	PART NO.	QTY.	1						76241	1
1	Divider Panel	G5926-10	1	X							
1a	M5X12 Hex Washer Head Philips (Not Shown)	S26641-4	4	X							
2	Heat Sink	M21756-11	1	X							
2a	M5X12 Combined Screw (Not Shown)	S28798-4	2	X							
3	Input Rectifier	M15454-25	1	X							
3a	M5X16 Combined Screw (Not Shown)	S28798-5	2	X							
3b	MOV Assembly (Not Shown)	S27147-5	1	X							
4	Grommet	T12380-4	2	X							
5	Auxiliary Transformer	M21437-12	1	X							
5a	M5X12 Combined Screw (Not Shown)	S28798-4	4	X							
6	Diode-Bridge	T13637-6	2	X							
6a	M5X12 Combined Screw (Not Shown)	S28798-4	2	X							
7	Control PC Board	S31221	1	X							
7a	M5X30 Combined Screw (Not Shown)	S28798-8	2	X							
8	Gas Control Harness (Not Shown)	G6043-33	1	X							
9	Aux Harness (Not Shown)	G6043-1	1	X							

NOTE: Use only the parts marked "X" in the column under the heading number called for in the model index page.

Index of Sub Assemblies
 Sub Assembly Illustration
 Index of Sub Assemblies
 Sub Assembly Illustration
 Index of Sub Assemblies
 Sub Assembly Illustration
 Index of Sub Assemblies
 Sub Assembly Illustration



OPTIMARC® CV350




ITEM	DESCRIPTION	PART NO.	QTY.	1						76241	1
1	Base	G5872-3	1	X							
2	Choke Assembly	L13166-5	1	X							
2a	M5X12 Combined Screw (Not Shown)	S28798-4	4	X							
3	Main Transformer Assembly	L15759-1	1	X							
3a	M5X16 Combined Screw (Not Shown)	S28798-5	4	X							
4	Output Rectifier Assembly, Includes:	L13174-8	1	X							
4a	Heatsink	M24710-10	1	X							
4b	Support Bracket	L13173-15	1	X							
4b-2	M5 Hex Head Screw (Not Shown)	S26641-6	3	X							
4b-3	M5 Plain Washer (Not Shown)	S26638-3	3	X							
4b-4	M5 Lock Washer (Not Shown)	S26639-3	3	X							
4c	Support Bracket	L13173-16	1	X							
4c-2	M5X30 Combined Screw (Not Shown)	S28798-8	1	X							
4d	Support Bracket	L13173-18	1	X							
4d-2	M5X30 Combined Screw (Not Shown)	S28798-8	1	X							
4e	Spacer	S26158	5	X							
4f	Spacer	S26157	5	X							
4g	Output Diodes	M15454-24	4	X							
4g-2	M6X16 Combined Screw (Not Shown)	S28798-7	8	X							
4h	Thermostat	T13359-26	1	X							
4h-2	M3X10 Combined Screw (Not Shown)	S28798-6	2	X							
4i	Aluminum Bar	M24712-4	1	X							
4j	Reconnect Panel Link	T14190-1	4	X							
4k	Copper Strap	S27092-1	2	X							
4k-2	M6X20 Screw (Not Shown)	S26641-37	2	X							
4k-3	M6 Plain Washer (Not Shown)	S26638-8	2	X							
4k-4	M6 Lock Washer (Not Shown)	S26639-11	2	X							
4k-5	M6 Hex Nut (Not Shown)	S26640-8	2	X							
4l	M5X12 Combined Screw (Not Shown)	S28798-4	4	X							
5	Resistor Assembly, Includes:	S27175-3	1	X							
5a	Resistor	M20716-7	1	X							
5b	M10 Bolt (Not Shown)	S26185-13	1	X							
5c	M10 Plain Washer (Not Shown)	S26638-6	1	X							
5d	M10 Lock Washer (Not Shown)	S26639-6	1	X							
5e	M10 Hex Nut (Not Shown)	S26640-6	1	X							
5f	PET (Not Shown)	S26787-4	2	X							
6a	Top Switchboard Bracket	M21756-9	1	X							
6a-2	M5X12 Combined Screw (Not Shown)	S28798-4	2	X							
6b	Heatsink	M24710-14	1	X							
6c	Bottom Switchboard Bracket	M21756-16	1	X							
6c-2	M5X12 Combined Screw (Not Shown)	S28798-4	3	X							
6d	Switchboard	S30254	1	X							
6e	Torx Button Head Screw (Not Shown)	S25930-8	6	X							
6f	M6 Plain Washer (Not Shown)	S26638-8	6	X							
6g	M6 Lock Washer (Not Shown)	S26639-11	6	X							
6h	Switchboard Harness (Not Shown)	G6043-45	1	X							
7	Thermostat Harness (Not Shown)	G6043-41	1	X							

NOTE: Use only the parts marked "X" in the column under the heading number called for in the model index page.

OPTIMARC® CV350




2017.04



ITEM	DESCRIPTION	PART NO.	QTY.	1					76241	1
1	Case Back Welded Assembly	G5873-12	1	X						
1a	M5X12 Hex Washer Head Philips (Not Shown)	S26641-4	1	X						
1b	ST4.8X13 Washer Faced Hex Self (Not Shown)	S26738-2	1	X						
2	Fan, Includes:	M22731-3	1	X						
2a	Fan Capacitor (Not Shown)	M22731-3-B	1	X						
2b	M5 Hex Head Screw (Not Shown)	S26641-5	4	X						
2c	M5 Plain Washer (Not Shown)	S26638-3	4	X						
2d	M5 Lock Washer (Not Shown)	S26639-3	4	X						
2e	M5 Hex Nut (Not Shown)	S26640-3	4	X						
2f	Fan Harness (Not Shown)	G6043-43	1	X						
3	Input Block	M20720-6	1	X						
3a	M4X30 Hex Washer Head Philips (Not Shown)	S26641-3	2	X						
3b	M4 Plain Washer (Not Shown)	S26638-2	4	X						
3c	M4 Lock Washer (Not Shown)	S26639-2	2	X						
3d	M4 Hex Nut (Not Shown)	S26640-2	2	X						
3e	Input Snubber Assembly (Not Shown)	S26781-2	1	X						
4	Cable Holder Base	M20720-5	1	X						
4a	M3 Pan Head Philips Screw (Not Shown)	S26641-11	2	X						
4b	M3 Plain Washer (Not Shown)	S26638-1	2	X						
4c	M3 Lock Washer (Not Shown)	S26639-1	2	X						
5	Cable Holder Cover	M20720-4	1	X						
5a	M4X30 Hex Washer Head Philips (Not Shown)	S26641-3	2	X						
6	Input Supply Box	M20720-2	1	X						
6a	M4X30 Hex Washer Head Philips (Not Shown)	S26641-3	2	X						
6b	M4 Plain Washer (Not Shown)	S26638-2	2	X						
6c	M4 Lock Washer (Not Shown)	S26639-2	2	X						
7	Receptacle	S26506-2	1	X						
8a	Fuse Holder	T12386-6	1	X						
8b	Fuse 2A (Not Shown)	T10728-20	1	X						
8c	Decal, Heater and Fuse (Not Shown)	S26743-2	1	X						
9	Decal, Connection Diagram (Not Shown)	S26724-1	1	X						
10	Ground Decal (Not Shown)	S26732	1	X						

NOTE: Use only the parts marked "X" in the column under the heading number called for in the model index page.



ITEM	DESCRIPTION	PART NO.	QTY.	1						76241	1
1	Left Case Side	G5879-4	1	X							
1a	M5X12 Hex Washer Head Philips (Not Shown)	S26641-4	5	X							
1b	ST4.8X13 Washer Faced Hex Self (Not Shown)	S26738-2	2	X							
2	Roof Welded Assembly	G5878-2	1	X							
2a	M5X12 Hex Washer Head Philips (Not Shown)	S26641-4	6	X							
2b	ST4.8X13 Washer Faced Hex Self (Not Shown)	S26738-2	4	X							
2c	Label (Not Shown)	M20952	1	X							
3	Wiring Diagram	NSS	1	X							
4	Right Case Side	G5880-5	1	X							
4a	M5X12 Hex Washer Head Philips (Not Shown)	S26641-4	5	X							
4b	ST4.8X13 Washer Faced Hex Self (Not Shown)	S26738-2	2	X							
5	LE Logo	NSS	2	X							

NOTE: Use only the parts marked "X" in the column under the heading number called for in the model index page.
NSS – Not Sold Separately

Index of Sub Assemblies
 Sub Assembly Illustration
 Index of Sub Assemblies
 Sub Assembly Illustration
 Index of Sub Assemblies
 Sub Assembly Illustration
 Index of Sub Assemblies
 Sub Assembly Illustration